## Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE \_\_yes \_\_no

1. Nam	e (indicate	preferred name)		
historic			•	
and/or common	ROBERT A. I	MARTIN HOUSE		
2. Loca	ition			
street & number	251 Pleasan	t Valley Road	· 	not for publication
city, town	Westminster	XX_ vicinity of	congressional district	Sixth
state	Maryland	county	Carroll	
3. Clas	sification	* * * * * * * * * * * * * * * * * * * *		
structure site object	Ownership public XX_ private both Public Acquisition in process being considered XX_not_applicabl		Present Use agriculture commercial educational entertainment government industrial military	museum park xx private residence religious scientific transportation other:
4. Own	er of Prop	erty (give names a	nd mailing addresse	es of <u>all</u> owners)
name Mr	. and Mrs. Rol	pert A. Martin		
street & number	251 Pleasan	t Valley Road	telephone n	o.: 848-7988
city, town	Westminster	state	and zip code Mai	cyland 21157
	tion of Le	gal Descripti	on	
courthouse, regis	stry of deeds, etc.	Carroll County Co	urthouse Annex	liber 552
street & number		55 N. Court Stree	t	folio 310
city, town		Westminster	state	Maryland
6. Repr	esentatio	n in Existing	Historical Surv	reys
title None		- · · · · · · · · · · · · · · · · · · ·		
te			federalsta	te county loca
depository for su	rvev records			- Journey - Total
city, town		· · · · · · · · · · · · · · · · · · ·		
orty, town			state	

Condition
\_\_\_\_excellent
XX good

\_\_\_ fair

\_\_\_ deteriorated \_\_ ruins \_\_ unexposed Check one
unaltered
XX altered

Check one

XX original site

\_\_ moved date of move

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Robert A. Martin House is a two-story, three bay SUMMARY: by two bay farmhouse on a fieldstone foundation. It is constructed of frame with brick insulation, although some of the exterior walls may be of log (according to oral interviews), and the exterior is currently covered in aluminum siding. It has a gable roof covered in standing seam sheet metal with rebuilt brick chimneys at each gable end. three bay main facade faces south and has a central entrance although the door was recently replaced by the present owner. Other bays on the main facade and on the east and west gable ends have tall six-over-six sash windows. The north facade contained a double-tiered porch that has been partially The architecture of the interior is fairly uniform in detailing from the late 19th century, including door moldings, window frames and box locks with 1880s patent dates. In the basement, log floor joists can be viewed towards the front of the house which may be reused timbers from an earlier Also in the basement is a large stone fireplace which seems unusual for a late 19th century farmhouse.

The farm complex includes several period outbuildings, although the large bank barn was destroyed when its roof was blown off during a hurricane. Only the foundation of the barn remains today. To the rear of the farmhouse is a one-story, board-and-batten washhouse which appear to be contemporary to the construction of the house. North of the washhouse is a 20th century chicken house and a board-and-batten smokehouse of recent construction. Adjoining the barn foundation is a wagon shed and on the north and east sides of the barn foundation are three concrete silos.

DESCRIPTION: The Robert A. Martin House is located on a hilltop north of Meadow Branch Road, approximately .5 mile west of Littlestown Pike. The farm complex sits at the end of a .7 mile long dirt lane, which was once part of a through road known as Shade's Schoolhouse Road. The hilltop site has a commanding view of the rolling Piedmont countryside to the south. While the surrounding land is primarily agricultural, the fields to the east of the farm complex composed an open pit limonite (iron ore) mine during the late 19th century. These iron ore banks are shown on the 1877 Illustrated Atlas of Carroll County when the property was owned by the Erb family. During the early 20th century, the open pit was used as a trash dump and in the mid-20th century the accumulated trash was cleaned out and the pit was filled-in with dirt.

Description (continued)

Survey No. CARR-1283

Section 7 Page 2

The farmhouse is a two-story, three bay by two bay structure on a fieldstone foundation. From renovation work done by a Robert A. Martin where the structure was exposed, it is constructed of frame with brick insulation. This was a popular framing technique in this region during the late 19th century. However, some of the exterior walls may be of log, according to an oral interview with Margaret B. Jordan who lived in the house from 1906 to 1919. She recalls that a log wall was exposed when putting in the stove. The exterior is currently covered in aluminum siding.

The house has a gable roof covered in standing seam sheet metal with rebuilt brick chimneys at each gable end. From the attic, it can be seen that the chimney on the east gable end has been reduced in size. The roof framing system is 2X3 rafters butted together without a ridge piece nor any mortise and tenons.

The three bay main facade faces south and has a central entrance. There is a full-length, one-story proch with a hipped roof supported by square posts. The central entrance has single pane transom but the door and side panels were recently installed by the present owner when the existing door blew down during a storm.

Other bays on the main facade and on the east and west gable ends have tall six-over-six sash windows. These windows are late 19th century in style and shape. The original wood frames are not exposed but are covered in aluminum siding.

The north facade contained a double-tiered porch which is formed by a projection (catslide) of the rear portion of the This porch has been completely enclosed except for a small section at first story level of the northwest corner. portion of the porch was enclosed at an earlier date, perhaps originally, to form a projecting pantry -- a feature that was popular in this region in the late 19th century. This is probably a later alteration to the house due to the fact that the back wall of the main block (within the enclosed porch) is covered in a five-inch wide weatherboard, while the pantry (also viewed within the enclosed porch) is covered in German siding. Margaret B. Jordan remembers that her father, J. Wesley Beggs, tore out the interior partition to convert the pantry to a kitchen during their residency in the house, 1906 to 1919.

The house currently has a three-room plan and interior remodeling of the west room (replastering of the walls, wall

Description (continued)

Survey No. CARR-1283

Section 7 Page 3

to wall carpet) prevents analysis for any indications for determining whether the original plan was four rooms. The -central partition through the house is enclosed stairways -both a front stair and back stair -- with doors opening off the stairs into each room and a small passage provided between the two stairways.

The mantelpieces have been removed from the house and the remaining woodwork -- serpentine molded window and door frames, bulbous bannisters and newel posts on the main stair, four paneled doors throughout the house -- are uniform in detailing from the late 19th century. The box locks are also fairly uniform throughout the house and have 1880s patent dates.

In the basement, log floor joists can be viewed towards the front of the house which may be reused timbers from an earlier structure. Also in the basement is a large stone fireplace which seems unusual for a late 19th century farmhouse. Historical documentation shows that there was a house on this property as early as 1840. One theory about the evolution of the house would be that there was a log structure on the site of the present house that was totally encapsulated by a major renovation of the structure circa 1890.

Historical archaeology at the Phase I level, however, did not turn up the range and type of artifacts for a site occupied as early as 1840. While these finding were not conclusive, the architectural analysis of the farmhouse provides documentation that the building, as it stands today is almost completely a circa 1890s structure.

The farm complex includes several period outbuildings, although the large bank barn was destroyed when its roof was blown off during a hurricane. Only the broad fieldstone foundation of the barn remains today. On the east gable end of the barn foundation is a concrete block foundation of a 20th century addition to the barn. One concrete silo is located east of the barn and two concrete silos are located on the north side. Attached to the west side of the barn is a row of frame machinery sheds: a shed-roofed tractor shed, a gable-roofed, board-and-batten wagon shed with cribs, and a shed-roofed garage. A modern metal horse barn sits east of this entire complex.

To the rear of the farmhouse is a one-story, board-and-batten washhouse which appear to be contemporary to the construction of the house. The washhouse has a rectangular plan with the

Survey No. CARR-1283

Section 7 Page 4

Description (continued)

dimensions 14 X 20 feet. It is constructed of frame on a fieldstone foundation and has a gable roof coveered in standing seam sheet metal. The south elevation faces the farmhouse and has a door, six-over-six window, and a one-story porch with shed roof. The east elevation has a three-over-six sash window and a six-pane window in the gable. The north elevation has a six-over-six sash window and the west elevation is unfenestrated. A brick chimney rises from the peak of the roof at the west gable end.

North of the washhouse is a small complex of domestic buildings. There is a frame chicken house with a shed roof. The windows of the chicken house, which face west, have been replaced. There is also a board-and-batten smokehouse built about 1975.

<u>8. S</u>	ignificance		Survey No. CARR-1283		
Period	-1599 agriculture -1699 XX architecture -1799 art -1899 commerce	Check and justify below Community planning Conservation C	law literature military music	science sculpture social/ humanitarian theater	
Specific	dates	Builder/Architect			
check:	Applicable Criteria: A and/or Applicable Exception:		E E C		

Prepare both a summary paragraph of significance and a general statement of history and support.

Level of Significance: national

HISTORY: The Robert A. Martin house, as it stands today, is primarily a late 19th century structure, and was most likely built about 1890. Historical documentation shows that the property had a farmhouse on it as early as 1840, and some remnants of the earlier structure may be reused as part of the existing structure. The property was subject to several Equity Court cases through the 19th century due to an unclear will of 1840. The field on the east side of the farm complex was a small open pit iron ore mine. The mine was in use as early as 1877, because it is indicated on the <a href="Illustrated Atlas">Illustrated County</a> published in that year.

state

loca1

HISTORY: The Robert A. Martin house is difficult to date. Architectural analysis of the structure presents clear evidence the the structure as it stands today is primarily a late 19th century building. Historical documentation shows that the property had a farmhouse on it as early as 1840. Phase I historical archaeology indicates that the earlier house on this property may have been located in a different location than the present house, based on the quantity and type of artifacts recovered in units dug at the rear of the current house adjoining the washhouse.

The architecture of the farmhouse is fairly uniform around a late 19th century date of construction, although some structural material may be reused from an earlier building, including log floor joists in the basement and evidence from oral interviews that some exterior walls are constructed of log. The possibility also exists that an original log house was completely enclosed in a late 19th century major renovation of the structure, especially in light of the large stone fireplace in the basement.

The Land Records of Carroll County show that the property comprising the Robert A. Martin House was under dispute for much of the 19th century. In 1840, Magdelena Rinehart died

Survey No. <u>CARR-1283</u> Section 8 Page 2

leaving her real property to her grandson and grandaughters. The grandsons renounced the inheritance, leaving the property to two minor grandchildren. In Equity Court case #336, the property was partitioned in two and the corresponding plats show that a farmhouse was located on each farm.

In 1864, questions were raised about the earlier partitioning, and the property was again sold under court order (Equity Court case #761). The 145 acre parcel was sold to John T. Erb for \$5700, the purchase price indicating that there were improvements on the property at that time.

The property remained in the Erb family until 1901, when it was in Equity Court again (case #3827) for default of a mortgage. While the land records provide no exact documentation of when the current improvements were made, they may have occurred around 1879 when Samuel Erb purchased the property from John T. Erb, or they may have occurred closer to 1901 if the mortgage which was in default was a mortgage taken to construct the current house. Architectural details of the house, including uniform moldings and cast iron box locks, suggest a date of circa 1890 for its construction.

The field on the east side of the farm complex was a small open pit iron ore mine. The mine is indicated on the 1877 Illustrated Atlas of Carroll County. Residents during the early 20th century recall the use of the open pit from the mine as a site for dumping trash. This was filed in with dirt by the Essich family in the mid-20th century.

Owners of the property during the 20th century were J. Wesley Beggs, John D. Kauffman, Charles F. Essich, Albert H. Essich, Charles J. Miller, Sr., and Robert A. Martin.

CARR-12 Robert	83 A. Martin Ho	ouse: Chain-of-Title
552/310	8/31/1973	C. J. Miller, Sr. to 13.434 a. Robert A. & Janet Martin
528/324	12/1/1972	Albert H. & Mary E. Essich to C. J. Miller, Sr.
192/149	10/14/1946	Charles F. & Cora Essich to 132 a. Albert H. & Mary E. Essich
155/167	2/13/1931	Anna V. Kauffman, widow, to Charles F. & Cora Essich
147/5	10/13/1925	J. Wesley & Clara S. Beggs to John D. & Anna V. Kauffman
100/130	8/15/1904	Westminster Savings Bank to 139 a. \$5570 J. Wesley & Clara S. Beggs
92/150	2/18/1901	E. Oliver Grimes, Assig. of Mortgage to Westminster Savings Bank 138 a. \$4160 Equity Court Case # 3827
40/379	3/25/1870	Samuel Erb, Trustee, to 145 a. \$5700 John T. Erb

Equity Court Case # 336, Estate of Magdelena Rinehart

Equity Court Case # 761

John T. Erb

## 9. Major Bibliographical References

Survey No. CARR-1283

Land and Equity Court Records of Carroll County, Maryland

Lake Griffin & Stevenson, <u>Illustrated Atlas of Carroll County</u>,

Maryland, 1877.

10. Ge	ographica	I Data					
Acreage of nomi	nated property						
Quadrangle nam	ne <u>New Windso</u>	r			Quadrang	e scale 1 : 2400	0
UTM References	do NOT complet	e UTM refere	ences				
A Zone Easti			В	one Eastin	g	Northing	
c		1111	ם	1111	11		
E			- F				
G L			н				
Verbal bounda	ry description and	justification					
	<del>-</del>			*			
List all states	and counties for pr	operties overla	pping state	or county b	oundaries		
state		code	county	e e		code	
state		code	county		w.	code	
11. For	m Prepar	ed By		:			• .
name/title	Joe Getty						
organization	Noodle-Doose	y Press		date	Novemb	er 1986	
street & number	P. 0. Box 7	16		telephone	(301)	374-2605	
city or town	Manchester			state I	Marylan	đ	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:


Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438





1. CARR-1283 ROBERT A. MARTIN HOUSE
2. Carroll County, Maryland
3. Joe Getty
4. November 1986
5. Md. Hist. Trust Appendix

5. Md. Hist. Trust, Annapolis, Md 6. S & W elev (camera fac NE) 7. 1/11



- CARR-1283 ROBERT A. MARTIN HOUSE
- Carroll County, Maryland
- Joe Getty
- November 1986
- Md. Hist. Trust, Annapolis, Md. E & N elev (camera fac sw) 2/11



- CARR-1283 ROBERT A. MARTIN HOUSE
- Carroll County, Maryland
- Joe Getty September 1986
- Md. Hist. Trust, Annapolis, Md
- - S elev. -- transom detail 3/11



CARR-1283 ROBERT A. MARTIN HOUSE Carroll County, Maryland

2. Carroll County, Marylan
3. Joe Getty
4. September 1986
5. Md. Hist. Trust, Annapo
6. S elev. -- front door

Md. Hist. Trust, Annapolis, Md. 7. 4/11



- CARR-1283 ROBERT A. MARTIN HOUSE
- Carroll County, Maryland
  - Joe Getty September 1986
- Md. Hist. Trust, Annapolis, Md.
- S elev -- window frame
- 7. 5/11



- CARR-1283 ROBERT A. MARTIN HOUSE
- Carroll County, Maryland
- 2. Carroll County, Marylan
  3. Joe Getty
  4. November 1986
  5. Md. Hist. Trust, Annapo
  6. Washhouse, s & e elev.
  7. 6/11 Md. Hist. Trust, Annapolis, Md.



- 1. CARR-1283 ROBERT A. MARTIN HOUSE
- 2. Carroll County, Maryland
- Joe Getty
- 4. November 1986
- 5. Md. Hist. Trust, Annapolis, Md.
- 6. Washhouse, n&w elev
- 7. 7/11



- . CARR-1283 ROBERT A. MARTIN HOUSE
- Carroll County, Maryland
   Joe Getty
- 4. September 1986
- 5. Md. Hist. Trust, Annapolis, Md.
- 6. Washhouse, S & w elev 7. 8/11



- CARR-1283 ROBERT A. MARTIN HOUSE
- Carroll County, Maryland
- Md. Hist. Trust, Annapolis, Md
- 2. Carroll County, Marylan
  3. Joe Getty
  4. September 1986
  5. Md. Hist. Trust, Annapo
  6. Wagon shed, S & w elev 7. 9/11



- CARR-1283 ROBERT A. MARTIN HOUSE
- Carroll County, Maryland Joe Getty
- September 1986
- 5. Md. Hist. Trust, Annapolis, Md. 6. Chicken house, W & S elev
- 10/11



- CARR-1283 ROBERT A. MARTIN HOUSE
- Carroll County, Maryland
- Joe Getty
- September 1986
- 2.34.56.7. Md. Hist. Trust, Annapolis, Md.
- Smokehouse, W & S elev
- 11/11